


<b>ENVIRONMENTAL MANAGEMENT SERVICES</b>			
<b>Review of Monitoring Results</b>			
<b>GENERAL</b>			
CLIENT:	<b>METROMIX PTY LTD</b>		
PROJECT NO./LOCATION:	<b>215 - MARRANGAROO</b>		
CONTACT PERSON:	<b>Mr Daniel Lythgo</b>		
<b>SAMPLES</b>			
Type:	<b>Deposited Dust</b>	No of Samples:	<b>3</b>
Sample Period	<b>02/05/2017 to 02/06/2017</b>	Date despatched :	<b>02/06/2017</b>
Submission Sheet received by Corkery & Co:	<b>No</b>		
Date Received by ALS	<b>02/06/2014</b>	Batch No:	<b>24006120</b>
Results Received by RWC <b>08/06/2017</b>			
<b>REVIEW OF RESULTS</b>			Comments
Results Entered/Accepted	<b>Yes</b>		
Comparison with Previous Results	<b>Yes</b>		
Statistical Analysis	<b>Yes</b>		
<b>DISTRIBUTION OF RESULTS</b>			
Result Sheets to Client:	<b>Yes</b>	Result Sheets to Residents:	<b>No</b>
Summary Sheets to Client:	<b>Yes</b>	Summary Sheets to Residents:	<b>No</b>
<b>COMMENTS</b>			
<p>Deposited dust monitoring results for the period from 4 April 2017 to 2 May 2017 indicate that deposited dust levels at point locations MD-2, MD-3, MD-4 and MD-5 are within approved EPA annual average guideline levels.</p>			
<b>ACTION</b>			
No action is necessary			
<b>SIGNED:</b>	 Andrea Kubin		<b>DATE: 8/06/2017</b>