

Metromix Teralba Quarry - Deposited Dust Monitoring Results

	RHONDDA RD			MYRTLE ST			HILLSIDE CRES			RODGERS ST			MARGARET ST		
Year	Total Insoluble Solids	Ash Fraction	% Ash	Total Insoluble Solids	Ash Fraction	% Ash	Total Insoluble Solids	Ash Fraction	% Ash	Total Insoluble Solids	Ash Fraction	% Ash	Total Insoluble Solids	Ash Fraction	% Ash
Units	g/m ² /month	g/m ² /month		g/m ² /month	g/m ² /month		g/m ² /month	g/m ² /month		g/m ² /month	g/m ² /month		g/m ² /month	g/m ² /month	
EPA Approved Level	4.0			4.0			4.0			4.0			4.0		
2004	1.3	0.9	73	0.9	0.6	70	2.5	1.3	68						
2005	1.4	0.9	69	1.3	0.7	58	1.4	0.7	54						
2006	1.0	0.6	67	2.0	1.1	50	0.9	0.5	57						
2007	1.1	0.7	65	0.9	0.5	56	1.0	0.5	56						
2008	1.0	0.6	61	0.9	0.5	63	1.0	0.5	50						
2009	1.4	0.9	63	1.4	1.0	65	2.1	1.3	54						
2010	1.1	0.8	72	0.7	0.5	74	1.0	0.4	44						
2011	1.0	0.7	73	1.1	0.5	51	1.1	0.5	53	1.0	0.7	80	0.8	0.7	74
2012	0.8	0.5	66	0.9	0.5	63	1.4	0.5	36	1.0	0.7	74	1.2	0.7	71
2013	1.0	0.7	73	0.9	0.6	68	1.3	0.5	39	1.0	0.7	77	1.3	0.8	64
2014	0.9	0.5	60	0.9	0.5	60	1.5	0.8	52	1.9	1.3	51	1.0	0.6	62
2014 Results															
03-Jan-14	2.4	1.4	58	1.6	0.9	56	2.3	0.8	35	3.5	2.0	57	2.7	1.3	48
03-Feb-14	0.6	0.3	50	0.7	0.4	57	0.9	0.4	44	1.0	0.4	40	0.4	0.3	75
03-Mar-14	1.6	1.0	63	1.0	0.5	50	1.8	1.1	61	2.4	1.6	67	0.9	0.6	67
01-Apr-14	0.5	0.2	40	0.6	0.5	83	0.7	0.3	43	0.7	0.4	57	0.9	0.9	100
01-May-14	0.3	0.2	67	0.5	0.2	40	0.6	0.2	33	0.3	<0.1	0	0.5	0.2	40
02-Jun-14	0.8	0.5	63	1.0	0.6	60	3.4	2.2	65	6.7	5.7	0	1.3	0.7	54
02-Jul-14	0.6	0.3	50	0.8	0.3	38	0.7	0.3	43	1.0	0.7	70	0.5	0.2	40
01-Aug-14	0.7	0.6	86	0.8	0.5	63	0.6	0.2	33	1.0	0.5	50	1.0	0.7	70
01-Sep-14	0.5	0.3	60	0.6	0.5	83	1.3	1.1	85	0.4	0.4	100	0.7	0.5	71
01-Oct-14	0.8	0.4	50	0.7	0.5	71	2.0	1.5	75	0.7	0.5	71	0.5	0.3	60
03-Nov-14	0.4	0.3	75	1.2	0.8	67	1.3	0.8	62	1.0	0.7	70	0.9	0.5	56
01-Dec-14	1.3	0.7	54	1.4	0.8	57	1.9	0.8	42	4.2	1.4	32	1.7	1.0	59

=Monitoring did not occur at this location until 2011.

