

Metromix Teralba Quarry - Deposited Dust Monitoring Results

Year	RHONDA RD			MYRTLE ST			HILLSIDE CRES			RODGERS ST			MARGARET ST		
	Total Insoluble Solids	Ash Fraction	% Ash	Total Insoluble Solids	Ash Fraction	% Ash	Total Insoluble Solids	Ash Fraction	% Ash	Total Insoluble Solids	Ash Fraction	% Ash	Total Insoluble Solids	Ash Fraction	% Ash
Units	g/m ² /month	g/m ² /month		g/m ² /month	g/m ² /month		g/m ² /month	g/m ² /month		g/m ² /month	g/m ² /month		g/m ² /month	g/m ² /month	
EPA Approved Level	4.0			4.0			4.0			4.0			4.0		
2004	1.3	0.9	73	0.9	0.6	70	2.5	1.3	68						
2005	1.4	0.9	69	1.3	0.7	58	1.4	0.7	54						
2006	1.0	0.6	67	2.0	1.1	50	0.9	0.5	57						
2007	1.1	0.7	65	0.9	0.5	56	1.0	0.5	56						
2008	1.0	0.6	61	0.9	0.5	63	1.0	0.5	50						
2009	1.4	0.9	63	1.4	1.0	65	2.1	1.3	54						
2010	1.1	0.8	72	0.7	0.5	74	1.0	0.4	44						
2011	1.0	0.7	73	1.1	0.5	51	1.1	0.5	53	1.0	0.7	80	0.8	0.7	74
2012	0.8	0.5	66	0.9	0.5	63	1.4	0.5	36	1.0	0.7	74	1.2	0.7	71
2013	1.0	0.7	73	0.9	0.6	68	1.3	0.5	39	1.0	0.7	77	1.3	0.8	64
2014	0.9	0.5	60	0.9	0.5	60	1.5	0.8	52	1.9	1.3	51	1.0	0.6	62
2015	1.0	0.5	50	1.7	1.2	68	1.7	1.0	54	0.9	0.6	66	1.0	0.7	64
2016	0.9	0.5	62	1.2	0.7	61	1.8	1.1	61	0.8	0.5	67	1.1	0.7	67
2017	0.9	0.5	49	1.5	1.0	62	2.0	1.1	53	1.8	1.1	57	1.2	0.7	58
Average (All Years)	1.0	0.6	64	1.2	0.7	62	1.4	0.7	52	1.2	0.8	67	1.1	0.7	65

2018 Results																
02-Jan-18		0.8	0.6	75	0.5	0.4	80	1.3	0.7	54	1.3	0.7	54	1.1	0.8	73
=Monitoring did not occur at this location until 2011.																

