

Metromix Teralba Quarry - Deposited Dust Monitoring Results

	RHONDA RD			MYRTLE ST			HILLSIDE CRES			RODGERS ST			YORK ST			MARGARET ST		
Year	Total Insoluble Solids	Ash Fraction	% Ash	Total Insoluble Solids	Ash Fraction	% Ash	Total Insoluble Solids	Ash Fraction	% Ash	Total Insoluble Solids	Ash Fraction	% Ash	Total Insoluble Solids	Ash Fraction	% Ash	Total Insoluble Solids	Ash Fraction	% Ash
Units	g/m ² /month	g/m ² /month		g/m ² /month	g/m ² /month		g/m ² /month	g/m ² /month		g/m ² /month	g/m ² /month		g/m ² /month	g/m ² /month		g/m ² /month	g/m ² /month	
EPA Approved Level	4.0			4.0			4.0			4.0			4.0			4.0		
2004	1.3	0.9	73	0.9	0.6	70	2.5	1.3	68									
2005	1.4	0.9	69	1.3	0.7	58	1.4	0.7	54									
2006	1.0	0.6	67	2.0	1.1	50	0.9	0.5	57									
2007	1.1	0.7	65	0.9	0.5	56	1.0	0.5	56									
2008	1.0	0.6	61	0.9	0.5	63	1.0	0.5	50									
2009	1.4	0.9	63	1.4	1.0	65	2.1	1.3	54									
2010	1.1	0.8	72	0.7	0.5	74	1.0	0.4	44									
2011	1.0	0.7	73	1.1	0.5	51	1.1	0.5	53	1.0	0.7	80				0.8	0.7	74
2012	0.8	0.5	66	0.9	0.5	63	1.4	0.5	36	1.0	0.7	74				1.2	0.7	71
2013	1.0	0.7	73	0.9	0.6	68	1.3	0.5	39	1.0	0.7	77				1.3	0.8	64
2014	0.9	0.5	60	0.9	0.5	60	1.5	0.8	52	1.9	1.3	51				1.0	0.6	62
2015	1.0	0.5	50	1.7	1.2	68	1.7	1.0	54	0.9	0.6	66				1.0	0.7	64
2016	0.9	0.5	62	1.2	0.7	61	1.8	1.1	61	0.8	0.5	67.3				1.1	0.7	66.6
2017	0.9	0.5	48.82	1.5	1.0	62.49	2.0	1.1	53	1.8	1.1	57.2				1.2	0.7	57.7
2018	0.9	0.5	56.35	1.0	0.6	65.06	2.1	1.2	52.38	1.11	0.60	56.29				1.14	0.78	69.28
2019	1.3	0.9	64.44	1.4	1.0	68.91	2.4	1.2	57.45	1.65	1.17	68.23	1.19	0.85	70.65	2.10	1.30	61.90
Average (All Years)	1.1	0.7	64	1.2	0.7	63	1.5	0.8	52	1.3	0.8	66	1.2	0.9	71	1.1	0.7	66

2020 Results

06-Jan-20	1.5	1.2	80	2.1	1.4	67	1.3	0.5	38	2.1	1.6	76	1.3	0.9	69		
=Monitoring did not occur at this location until 2011.																	
=Monitoring location has been relocated.																	
=Monitoring started in March 2019																	

