Metromix Teralba Quarry - Deposited Dust Monitoring Results

	RHONDA RD			MYRTLE ST			HILLSIDE CRES			RODGERS ST			MARGARET ST		
Year	Total Insoluble Solids	Ash Fraction	% Ash	Total Insoluble Solids	Ash Fraction	% Ash	Total Insoluble Solids	Ash Fraction	% Ash	Total Insoluble Solids	Ash Fraction	% Ash	Total Insoluble Solids	Ash Fraction	% Ash
Units	$g/m^2/month$	$g/m^2/month$		$g/m^2/month$	$g/m^2/month$		$g/m^2/month$	$g/m^2/month$		$g/m^2/month$	$g/m^2/month$		$g/m^2/month$	$g/m^2/month$	
EPA Approved Level	**4.0**			**4.0**			**4.0**			**4.0**			**4.0**		
2004	1.3	0.9	73	0.9	0.6	70	2.5	1.3	68						
2005	1.4	0.9	69	1.3	0.7	58	1.4	0.7	54						
2006	1.0	0.6	67	2.0	1.1	50	0.9	0.5	57						
2007	1.1	0.7	65	0.9	0.5	56	1.0	0.5	56						
2008	1.0	0.6	61	0.9	0.5	63	1.0	0.5	50						
2009	1.4	0.9	63	1.4	1.0	65	2.1	1.3	54						
2010	1.1	0.8	72	0.7	0.5	74	1.0	0.4	44						
2011	1.0	0.7	73	1.1	0.5	51	1.1	0.5	53	1.0	0.7	80	0.8	0.7	74
2012	0.8	0.5	66	0.9	0.5	63	1.4	0.5	36	1.0	0.7	74	1.2	0.7	71
2013	1.0	0.7	73	0.9	0.6	68	1.3	0.5	39	1.0	0.7	77	1.3	0.8	64
2014	0.9	0.5	60	0.9	0.5	60	1.5	0.8	52	1.9	1.3	51	1.0	0.6	62
2015	1.0	0.5	50	1.7	1.2	68	1.7	1.0	54	0.9	0.6	66	1.0	0.7	64
2016	0.87	0.52	62	1.2	0.7	60.81	1.8	1.1	60.88	0.83	0.48	67.27	1.13	0.73	66.63
Average (All Years)	**1.1**	**0.7**	**66**	**1.1**	**0.7**	**62**	**1.4**	**0.7**	**51**	**1.1**	**0.7**	**68**	**1.1**	**0.7**	**66**

2016 Results															
09-Jan-17	1.1	0.5	45	1.0	0.6	60	1.4	0.8	57	0.6	0.4	67	0.8	0.4	50

=Monitoring did not occur at this location until 2011.